


KL QK540

2019 VW CARAVELLE 9 PAX



CHASIS # WV2ZZZ7HZKH055307

DEFICIENCIES: Accident (rear impact) engine starts and runs vehicle is able to move under its own power. This vehicle is officially totaled however engine wheels and interior are all in great shape. Glass is intact other than the rear hatch

KM 101,431

MIN BID \$6,500.00

KL NN149

2010 IVECO EUROCARGO LIFTGATE TRUCK



CHASIS # ZCFA75B0402572042

**DEFICIENCIES: BATTERIES,
RUST, ELECTRICAL
TACHOMETER INOP**

KM 31,000

MIN BID \$6,500.00

BIR AG96

2010 IVECO EUROCARGO LIGHTGATE TRUCK

CHASIS # ZCFA75B0402572045

**DEFICIENCIES: BATTERIES,
RUST, ELECTRICAL**

KM 34,674



MIN BID \$6,500.00

KL CJ948

2010 OPEL ASTRA

CHASIS # WOLOAHL35A2085932

**DEFICIENCIES: RUST
BATTERY**

KM 197,891



MIN BID \$2,400.00

KL WH397

2010 OPEL ASTRA

CHASIS # WOLOAHL35A2094228



**DEFICIENCIES: RUST
BATTERY**

KM 149,299

MIN BID \$2,400.00

KL CK328

2010 OPEL ASTRA

CHASIS # WOLOAHL35A2085944



**DEFICIENCIES: RUST
BATTERY**

KM 200,518

MIN BID \$2,400.00

BIR IM68

2010 OPEL ASTRA

CHASIS # WOLOAHL35A5052166



**DEFICIENCIES: RUST
BATTERY**

KM 72,249

MIN BID \$2,400.00

BIR LR56

2009 FORD F-150 PICKUP TRUCK



CHASIS # 1FTRF1W99KC31930

**DEFICIENCIES: BODY RUST,
UNDER BODY RUST
MARDER DAMAGE ENGINE
COMPARTMENT. ENGINE
RUNS AND DRIVES**

56,500 MILES

MIN BID \$2,200.00

BIR FO36



2010 OPEL VIVARO 9 PAX

CHASIS # WOLJ7AMA6BV603400

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 98,597

MIN BID \$2,900.00

BIR AN89



2010 OPEL VIVARO 9 PAX

CHASIS # WOLJ7AMA6BV603413

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 103,440

KL KJ267



2010 OPEL VIVARO 9 PAX

CHASIS # WOLJ7AMA6BV602922

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 199,708

MIN BID \$2,900.00

KL JW848



2010 OPEL VIVARO 9 PAX

CHASIS # WOLJ7AMA6BV603042

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 148,535

MIN BID \$2,900.00

KL UJ534



2010 OPEL VIVARO 9 PAX

CHASIS # WOLJ7AMA6BV603909

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL GLOW
PLUGS. RUNS AND DRIVES**

KM 58,461

MIN BID \$2,900.00

KL FB407



2010 FAT DUCATO VAN

CHASIS # ZFA25000001833787

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. NEW
CLUTCH RUNS AND DRIVES**

KM 87,461

MIN BID \$2,600.00

KL IP346



2010 FIAT DUCATO CARGO VAN

CHASIS # ZFA25000001823515

**DEFICIENCIES: BATTERY,
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 147,903

MIN BID \$2,600.00

KL UB354

2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV604281



**DEFICIENCIES: BATTERY
RUST ELECTRICAL,
SLIDING DOOR HANDLE
BROKEN, RUNS AND
DRIVES**

KM 70,295

MIN BID \$2,500.00

KL KF495



2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV604356

**DEFICIENCIES: BATTERY
RUST ELECTRICAL. RUNS
AND DRIVES**

KM 94,710

MIN BID \$2,500.00

KL FH265

2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV603603



**DEFICIENCIES: BATTERY
RUST ELECTRICAL, RUNS
AND DRIVES**

KM 36,634

MIN BID \$2,500.00

KL AZ431



2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV604290

**DEFICIENCIES: BATTERY
ELECTRICAL RUST, RUNS
AND DRIVES**

KM 69,809

MIN BID \$2,500.00

KL KK567

2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV604000

**DEFICIENCIES: BATTERY
RUST ELECTRICAL, RUNS
AND DRIVES**

KM 119,533



MIN BID \$2,500.00

KL WH779



2010 OPEL VIVARO CARGO VAN

CHASIS # WOLF7AMA6BV604373

**DEFICIENCIES: BATTERY
RUST ELECTRICAL, RUNS
AND DRIVES**

KM 101,419

MIN BID \$2,500.00